

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402747647

Date Received:

07/14/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 3 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: PO BOX 370

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name Phone

COGCC Inspection Reports

Scott Ramsey

Bud Thompson

Email

COGCCInspectionReports@terraep.com

scott.ramsey@state.co.us

BLThomps@BLM.gov

COGCC INSPECTION SUMMARY:

FIR Document Number: 700702968

Inspection Date: 07/12/2021

FIR Submit Date: 07/13/2021

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: URSA OPERATING COMPANY LLC

Company Number: 10447

Address: 950 17TH STREET, SUITE 1900

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 335681

Location Name: BOIES-62S98W Number: 24SWSW County: \_\_\_\_\_

Qtrqr: SWS Sec: 24 Twp: 2S Range: 98W Meridian: 6

Latitude: 39.856397 Longitude: -108.348116

FACILITY - API Number: 05-103- -00 Facility ID: 335681

Facility Name: BOIES-62S98W Number: 24SWSW

Qtrqr: SWS Sec: 24 Twp: 2S Range: 98W Meridian: 6

Latitude: 39.856397 Longitude: -108.348116

CORRECTIVE ACTIONS:

3 ☒ CA# 152720

Corrective Action: Install or repair required BMPs

Date: 09/13/2021

Response: CA COMPLETED

Date of Completion: 07/14/2021

This corrective action states that the cut slope shows signs of lack of stabilization. The cut slope will be addressed at the time interim reclamation is performed at this location. Per an approved Sundry and Variance

Operator Comment: request submitted by the previous operator (URSA), interim reclamation for this location must be completed by 5/23/22. The approved Sundry and Variance Request documents are attached. TEP will complete the interim reclamation for this location prior to 5/23/22, which will mitigate any stabilization concerns related to the cut slope.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment: CA 152720 has been addressed. Per the approved Interim Reclamation Variance Request, TEP will complete the interim reclamation activities for this location before 5/23/22. Issues / concerns with cut slope stability will be mitigated once interim reclamation activities have been completed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Gardner

Signed: \_\_\_\_\_

Title: TEP ENV

Date: 7/14/2021 4:27:05 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<b><u>Document Number</u></b>	<b><u>Description</u></b>
402747647	FIR RESOLUTION SUBMITTED
402747657	Variance Request Letter from URSA to COGCC
402747658	Approved Form 4 - Interim Recl. Variance Request

Total Attach: 3 Files