



Muleherder 14-14



Installed appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2).

Conducted maintenance on equipment, cleaned up stained material and reviewed self-inspection processes Complied with Rule 1002,(2).D.