

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/27/2021

Submitted Date:

07/29/2021

Document Number:

701101779**FIELD INSPECTION FORM**Loc ID 315156 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10654

Name of Operator: LASSO OIL & GAS LLC

Address: 3021 RIDGE RD #156

City: ROCKWALL State: TX Zip: 75032

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

11 Number of Comments

7 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Boulger, Levin	970-509-0256	lboulger@31operating.com	
Thompson, Bud		BLThomps@BLM.gov	
, Engineering		dnr_cogccengineering@state.co.us	All engineering
Pesicka, Conor		conor.pesicka@state.co.us	
Freeman, Kris	(254) 717-0435	kfreeman@31operating.com	
Rosenberg, Kelly		kelly.rosenberg@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
230340	WELL	PR	11/08/2000	GW	103-08000	CONTINENTAL 2-16	PR

General Comment:

COGCC Follow Up Inspection Report Summary Location is within a Rule 1202.d Mule deer migration corridor and a Black bear area.

Follow up to 12/22/2020 inspection # 700404712

Uncorrected action item(s)

• Most recent meter calibration on 6-14-2019.

• Bradenhead access is not present.

During this inspection the following compliance issues were observed:

• Sign missing information. No API #. No EMS contact (911) Legal description does not match COGCC records.

• Weeds on location.

• Unused equipment on location. Used pipes and cables. 2 rods in the ground purpose unclear.

• Deadmen markers not brightly colored. Deadman at entrance marker is laying next to it.

• Storm water erosion on south edge of location.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

LocationOverall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign missing information. No API #. No EMS contact (911) Legal description does not match COGCC records.		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	08/30/2021

Emergency Contact Number:			
Comment:	911 800-209-9762		
Corrective Action:		Date:	

Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment on location. Used pipes and cables. 2 rods in the ground. Purpose unclear.		
Corrective Action:	Comply with 606	Date:	08/14/2021
Type	WEEDS		
Comment:	Weeds on location.		
Corrective Action:	Comply with Rule 606	Date:	08/14/2021

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Gas Meter Run	# 1		
Comment:	Most recent meter calibration on 6-14-2019.		
Corrective Action:	Calibrate gas metering equipment annually to comply with rule 430.d.(1).	Date:	02/01/2021
Type: Bradenhead	# 0		
Comment:	Bradenhead access is not present.		
Corrective Action:	Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2).	Date:	02/01/2021
Type: Deadman # & Marked	# 4		
Comment:	Deadmen markers not brightly colored. Deadman at entrance marker is laying next to it.		
Corrective Action:	Install proper guy line markers per Rule 1003.a	Date:	08/14/2021

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	230340	Type:	WELL	API Number:	103-08000	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches						
Compaction						

Comment: [Storm water erosion on south edge of location.](#)Corrective Action: [Install or repair required BMPs per Rule 1002.f.\(2\)C](#)

Date: 08/14/2021

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402765028	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5493322
701101785	Inspection 701101779 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5493318