

APACHE CANYON 04-13 API# 05-071-09582 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: AUGUST 05, 2021
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 698701915




PHOTO 1: THE FADED LOCATION SIGN WAS REPLACED WITH A NEW ONE.

APACHE CANYON 04-13 API# 05-071-09582 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: OCTOBER 10, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 698701915



PHOTO 2: BIRD NETTING WAS INSTALLED ACROSS THE TOP OF THE OPEN TOP WATER TANK.

APACHE CANYON 04-13 API# 05-071-09582 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: OCTOBER 10, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 698701915



PHOTO 3: THE HARDPAN STAINS ON THE GROUND NEAR THE WELL HEAD WAS REMOVED FROM THE LOCATION.

APACHE CANYON 04-13 API# 05-071-09582 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: OCTOBER 10, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 698701915



PHOTO 4: THE IMPACTED SOIL NEAR THE ENGINE SKID WAS REMOVED AND PROPERLY DISPOSED IN ACCORDANCE WITH THE OGRIS OPERATING WASTE MANAGEMENT PLAN.

APACHE CANYON 04-13 API# 05-071-09582 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: OCTOBER 10, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 698701915



PHOTO 5: THE IMPACTED SOIL NEAR THE ENGINE SKID WAS REMOVED AND PROPERLY DISPOSED IN ACCORDANCE WITH THE OGRIS OPERATING WASTE MANAGEMENT PLAN.