

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/28/2021

Submitted Date:

08/03/2021

Document Number:

700900615

FIELD INSPECTION FORM

Loc ID 319972 Inspector Name: Finkenbinder, Chane On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10695
Name of Operator: BEHRENS RESOURCES INC
Address: PO BOX 188
City: DEER TRAIL State: CO Zip: 80135

Findings:

- 12 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		dnr_cogccenforcement@state.co.us	For CA Matrix Inspection Routing
Behrens, Vic	303-810-6382	behrens@netecin.net	Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
202061	WELL	SI	06/01/2018	GW	001-07466	FARM RANCH EXPLORATION 1	PR

General Comment:

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Adequate		
Corrective Action:		Date:	_____

Good Housekeeping:			
Type	WEEDS		
Comment:	Weeds across the location		
Corrective Action:	Weeds. Location is within a designated setback location, remove trash or debris per Rule 604.c.(2)P.	Date:	08/13/2021

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

Multiple Spills and Releases?

Equipment:			corrective date
Type: Emission Control Device	# 1		
Comment:	stained soil. Control and contain spills/releases and clean up per Rule 906.a.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a.		Date: 08/13/2021
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Vertical Heated Separator	# 1		

Comment:	
Corrective Action:	Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs	Open Top		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		39.833504,-104.536454
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate
Comment: Inadequate berms around tank(s)				
Corrective Action: Repair or install berms or other secondary containment devices per Rule 605.a.(4).				Date: 08/31/2021

Wells Served By Facilities Above

API Number
001-07888
001-07466
001-07672

AirsID

API Number	AirsID

Venting:

Yes/No	NO	
Comment:		

Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 202061 Type: WELL API Number: 001-07466 Status: SI Insp. Status: PR

Producing Well

Comment: PR

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: _____ Annual Brhd Completed? _____

Last Brhd Test Results Initial Surf Csg Pressure: _____ Fluid Type: _____

End Surf Csg Pressure: _____

Comment: Appears to be plumbed to surface

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Wednesday July 28, 2021 at approximately 10:30am. I, Inspector Chane Finkenbinder, conducted an on-site inspection at Farm Ranch Exploration 1, Behrens Resources INC. at API # 001-07466 in Adams County Colorado. While there, I observed a producing well. During this inspection the following possible compliance issues were observed: No action has been taken to correct the issues from 5/22/2020 inspection DOC# 700900095. See photos # 1-6. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	finkenbc	08/03/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402769570	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5497139
700900616	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5497134