

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402776667

Date Received:

08/11/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 3 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Victoria Dizghinjili

Phone

303-825-4822

Email

vdizghinjili@kpk.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 697601485

Inspection Date: 08/05/2021

FIR Submit Date: 08/06/2021

FIR Status: _____

Inspected Operator Information:

Company Name: KP KAUFFMAN COMPANY INC

Company Number: 46290

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: _____

Location Name: _____ Number: _____ County: _____

Qtrqr: NWNE Sec: 20 Twp: 2N Range: 66W Meridian: 6

Latitude: 40.129619 Longitude: -104.798581

FACILITY - API Number: 05-123-00 Facility ID: 476987

Facility Name: NESSSU CONSOLIDATION Number: _____

Qtrqr: NWNE Sec: 20 Twp: 2N Range: 66W Meridian: 6

Latitude: 40.129619 Longitude: -104.798581

CORRECTIVE ACTIONS:

1 CA# 154620

Corrective Action: corrective action data as in previous inspection
Comply with rule 606

Date: 07/02/2021

Response: CA COMPLETED

Date of Completion: 08/09/2021

Operator Comment: Weeds overwhelming work area and present around open excavation have been removed. Please see attached pictures.

COGCC Decision: _____

COGCC
Representative:

3 CA# 154622

Corrective Action: corrective action date remains as in past inspection
Repair and maintain best management practices to control and contain all spills/releases of E&P waste to protect the environment, public health, safety and welfare and the environment as required by rule 913.b(5)B.i which requires that Operators will fence or cover open remediation excavations to prevent access when sites are not attended. The site was not attended at the time of the inspection

Date: 05/17/2021

Response: CA COMPLETED

Date of Completion: 08/09/2021

Operator Comment: Poly pipe has been replaced with fiberglass pipe. The excavation will be filled after re-inspection. The fencing has been reinstalled around. Please see attached pictures.

COGCC Decision:

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Victoria Dizghinjili

Signed:

Title: Engineering Tech

Date: 8/11/2021 12:07:33 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402776736	CA completed PIC1
402776737	CA completed PIC2

Total Attach: 2 Files