

Location

Lease Road:			
Type	Access		
comment:	Weeds/ Vegetation is grown on the access road from entrance of the main road to the well needs to be removed for good housekeeping.		
Corrective Action	Comply with Rule 606	Date:	08/24/2021

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Yellow "LTSI" variance tag		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Adequate		
Corrective Action:		Date:	

Overall Good:

Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			

Fencing/:			
Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			

Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 288601 Type: WELL API Number: 123-24625 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 08/14/2019 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: -- Fluid Type: _____

End Surf Csg Pressure: --

Comment: No updated annaul bradenhead test on file. Submit reports.

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Wednesday 8/11/21 at approximately 1014hrs, I, Inspector Adam Burns, Conducted an on-site inspection at Herbst C 27-19 of Noble Energy, at Location ID # 306423 in Weld County, Colorado. During this inspection the following possible compliance issues were observed: Weeds/ Vegetation is grown on the access road from entrance of the main road to the well needs to be removed for good housekeeping. Comply with Rule 606. With a corrective action date of 8/24/21 See attached photos. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	burnsa	08/13/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699104265	Inspection Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5505438