



99999999

REV. 7-64

GAS CONSERVATION COMMISSION
DEPARTMENT OF NATURAL RESOURCES
OF THE STATE OF COLORADO

NOV 8 1971

075-06431

File in duplicate for Patented and Federal lands.
File in triplicate for State lands.

COLORADO OIL & GAS COM. COMM.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	5. LEASE DESIGNATION AND SERIAL NO.
2. NAME OF OPERATOR The Bovaird Supply Company	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR Box 1032 Kimball, Nebraska 69145	7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 2031 fnl 845 fnl	8. FARM OR LEASE NAME Green
14. PERMIT NO.	9. WELL NO. 1
15. ELEVATIONS (Show whether DF, RT, GR, etc.)	10. FIELD AND POOL, OR WILDCAT MT HOPE EAST
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA SW NW Sec 20, T9N, R53W
	12. COUNTY Logan
	13. STATE Colorado

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT

(Other)

Plugging

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Date of work **October 14, 1971****Dumped Sand Across Perf. & 5 Sacks Cement Plug --9# Mud Between Plugs--
10 Across Surface Casing Shoe -- 10 Sacks at Top -- Weld Plate on Tope
of Surface.**

PERFORATION: J-1 Sand 5032-34' & 5048-52'

TD --5120

PBTD -- 5090

Ex Oil Prod.

DVR	
FJP	
HUM	
JAM	
JJD	



00817829

18. I hereby certify that the foregoing is true and correct

SIGNED **J. A. Peterson**TITLE **Store Manager**DATE **11-5-71**

(This space for Federal or State office use)

APPROVED BY **[Signature]**
CONDITIONS OF APPROVAL, IF ANY:TITLE **DIRECTOR**
O & G COM. COMM.DATE **NOV 12 1971**