

GOLDEN EAGLE 30-14 API# 05-071-08650 – OGRIS OPERATING  
OGCC OPERATOR NUMBER 10758 - DATE: AUGUST 16, 2021  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695103419



PHOTO 1: THE SCRUBBER LIQUID WAS REMOVED FROM THE PRODUCED WATER TANK AND DISPOSED OF IN ACCORDANCE WITH OGRIS'S WASTE MANAGEMENT PLAN AND THE COGCC RULES AND REGULATIONS.

GOLDEN EAGLE 30-14 API# 05-071-08650 – OGRIS OPERATING  
OGCC OPERATOR NUMBER 10758 - DATE: AUGUST 16, 2021  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695103419



PHOTO 2: THE FLUID ACCUMULATION THAT WAS FOUND INSIDE THE CONTAINMENT RESERVIOR ON THE SKID WAS REMOVED FROM THE LIQUID RING COMPRESSOR.

GOLDEN EAGLE 30-14 API# 05-071-08650 – OGRIS OPERATING  
OGCC OPERATOR NUMBER 10758 - DATE: AUGUST 16, 2021  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695103419



PHOTO 3: THE LEAK ON THE COMPRESSOR WAS REPAIRED. ALL FITTINGS ARE SECURLY FASTENED. THE FLUID ACCUMULATION WAS REMOVED FROM THE CONTAINMENT.