



## Excavated Area Map (w/ BH & PH) Government Equity 298-26-1

39.851945, -108.366794  
Section 26, Township 2 South, Range 98 West

### Mapped Features

- Borehole Location (Hydrocarbon Exceeding 910-1)
- Borehole Location (Hydrocarbons Below 910-1)
- ◆ Pot-Hole Site Investigation (Impacts observed)
- ◆ Pot-hole Site Investigation (No Impacts Observed)
- Excavated Area
- - - Additionally Excavated Area

DISCLAIMER: This representation and the Geographic Information System (GIS) used to create it are designed as a source of reference and not intended to replace official records and/or legal surveys. HRL assumes no responsibility for any risks, dangers, or liabilities that may result from its use and makes no guarantees as to the quality or accuracy of the underlying data.



**HRL**  
COMPLIANCE  
SOLUTIONS

Author: K. Rowe  
Revision: 0  
Date: 8.12.2021