

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/11/2021

Submitted Date:

08/11/2021

Document Number:

699803539

**FIELD INSPECTION FORM**

Loc ID 335241 Inspector Name: De Paolo, Corey On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

21 Number of Comments

3 Number of Corrective Actions

Corrective Action Response Requested

**Operator Information:**

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: PO BOX 370

City: PARACHUTE State: CO Zip: 81635

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211078	WELL	PR	05/31/1994	GW	045-06836	UNOCAL GR 32-32	PR
299025	WELL	PR	10/15/2008	GW	045-17541	WILLIAMS GM 42-32	PR
299030	WELL	PR	04/30/2009	GW	045-17542	WILLIAMS GM 342-32	PR
299031	WELL	PR	10/16/2008	GW	045-17543	WILLIAMS GM 332-32	PR

**General Comment:**

COGCC Inspection Report Summary  
 On Wednesday 8/11/21 at approximately 14:00 hours, I, Inspector Corey De Paolo, Conducted an on-site inspection at TEP ROCKY MOUNTAIN LLC UNOCAL-66S96W /32SWNE, Location #335241 in Garfield County Colorado.  
 While there, I observed normal production operations.  
 During this inspection the following compliance issues were observed:

- 1) Battery sign weathered and not legible with a corrective action date of 10/11/21.
- 2) Separator missing required information with a corrective action date of 10/11/21.
- 3) Location lacks stabilization. Insufficient tracking BMP at entrance to location with a corrective action date of 8/26/21.

- Location is located in a high priority habitat area. All drainages contribute to Parachute creek.

A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.  
 This is a summary of inspection report.

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	Separators missing required information.		
Corrective Action:	Containers that are used to store, treat, or otherwise handle a hazardous material and which are required to be marked, placarded, or labeled.	Date:	10/11/2021
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Battery sign weathered and not legible.		
Corrective Action:	Operators will ensure that signs are well maintained and legible, and will replace damaged signs.	Date:	10/11/2021
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	911/970-285-9377		
Corrective Action:		Date:	_____

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: \_\_\_\_\_

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Plunger Lift	# 4		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Type: Gas Meter Run	# 4		

Comment:	All meter runs have been calibrated in the last year		Date:	
Corrective Action:			Date:	
Type: Bradenhead	# 4			
Comment:	No form of pressure monitoring equipment located on braden heads. All braden head valves are accessible.		Date:	
Corrective Action:			Date:	
Type: Horizontal Heated Separator	# 5			
Comment:			Date:	
Corrective Action:			Date:	
Type: Bird Protectors	# 3			
Comment:			Date:	
Corrective Action:			Date:	
Type: Deadman # & Marked	# 1			
Comment:			Date:	
Corrective Action:			Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Centralized containment			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:	Centralized containment				
Corrective Action:				Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	<u>211078</u>	Type:	<u>WELL</u>	API Number:	<u>045-06836</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>Producing</u>								
Corrective Action:					Date:				
Facility ID:	<u>299025</u>	Type:	<u>WELL</u>	API Number:	<u>045-17541</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>Producing</u>								
Corrective Action:					Date:				
Facility ID:	<u>299030</u>	Type:	<u>WELL</u>	API Number:	<u>045-17542</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>Producing</u>								
Corrective Action:					Date:				
Facility ID:	<u>299031</u>	Type:	<u>WELL</u>	API Number:	<u>045-17543</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>Producing</u>								
Corrective Action:					Date:				

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches						
Gravel	Fail					Gravel insufficient
Sediment Traps						
		Ditches				
		Sediment Traps				
		Gravel				
		Compaction				
		Berms				
Compaction	Fail					Location lacks stabilization.
		Culverts				
Other	Fail					Insufficient tracking BMP at entrance to location.
Berms						

Comment: [Location lacks stabilization. Insufficient tracking BMP at entrance to location.](#)

Corrective Action: [Oil and gas operators shall implement and maintain Best Management Practices \(BMPs\) at all oil and gas locations.](#)

Date: 08/26/2021

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<a href="#">Refer to Sign/Markers and Storm water for corrective actions.</a>	depaoloc	08/11/2021

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402779794	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5505814">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5505814</a>
699803540	Photos for Insp. #699803539	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5505796">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5505796</a>