

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402795472

Date Received:

08/28/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 6 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Victoria Dizghinjili

Phone

303-825-4822

Email

vdizghinjili@kpk.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 691201525

Inspection Date: 08/23/2021

FIR Submit Date: 08/26/2021

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: KP KAUFFMAN COMPANY INC

Company Number: 46290

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: \_\_\_\_\_

Location Name: \_\_\_\_\_ Number: \_\_\_\_\_ County: \_\_\_\_\_

Qtrqr: NESW Sec: 1 Twp: 1N Range: 68W Meridian: 6

Latitude: 40.080399 Longitude: -104.956453

FACILITY - API Number: 05-123-00 Facility ID: 474780

Facility Name: Cosslett #3 Number: \_\_\_\_\_

Qtrqr: NESW Sec: 1 Twp: 1N Range: 68W Meridian: 6

Latitude: 40.080399 Longitude: -104.956453

CORRECTIVE ACTIONS:

1 ☒ CA# 155209

Corrective Action: Maintain vehicle tracking BMPs on the oil and gas location to comply with rule 1002.f. (2)F. Additionally, as material is tracked onto county or public roads, Operator shall contact the appropriate authority.

Date: 08/27/2021

Response: CA COMPLETED

Date of Completion: 08/27/2021

Operator  
Comment:

Tracking pad has been installed at access. Please see attached pictures.

COGCC Decision: Approved

COGCC  
Representative:

3 ☒ CA# 155211

Corrective Action: Manage waste in compliance with Rule 913.b.(5)i-v and COGCC Guidance 913.b.(5)B i-v.

Date: 08/27/2021

Response: CA COMPLETED

Date of Completion: 08/27/2021

Operator  
Comment: Fencing has been put up around excavations. Trash has been removed too. Please see attached pictures.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative: Per comment on FIR: "Soils piled on location. An unconsolidated earthen berm has been constructed around the spoils pile. However, this is inadequate to control runoff." Photographed fencing is adequate for access control, not stormwater control.

5 ☒ CA# 155213

Corrective Action:

Date: \_\_\_\_\_

Response: CA COMPLETED

Date of Completion: 08/27/2021

Operator  
Comment: Trash has been removed from location.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Victoria Dizghinjili

Signed: \_\_\_\_\_

Title: Engineering Tech

Date: 8/28/2021 2:58:06 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402795472	FIR RESOLUTION SUBMITTED
402795474	Tracking pad PIC1
402795475	Fencing re-installed PIC2
402795476	Fencing re-installed PIC3

Total Attach: 4 Files