

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402796449

Date Received:
08/30/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10433

Name of Operator: LARAMIE ENERGY LLC

Address: 1001 17TH STREET #1900

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Christina Pierce</u>	<u>970-263-3626</u>	<u>cpierce@Laramie-Energy.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 696202101

Inspection Date: 12/08/2020

FIR Submit Date: 12/09/2020

FIR Status: _____

Inspected Operator Information:

Company Name: LARAMIE ENERGY LLC

Company Number: 10433

Address: 1401 17TH STREET SUITE #1400

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 324315

Location Name: CC Number: 0610-22-43 County: _____
Pad

Qtrqtr: SENW Sec: 10 Twp: 6S Range: 97W Meridian: 6

Latitude: 39.539277 Longitude: -108.207040

FACILITY - API Number: 05-045-00 Facility ID: 324315

Facility Name: CC Number: 0610-22-43
Pad

Qtrqtr: SENW Sec: 10 Twp: 6S Range: 97W Meridian: 6

Latitude: 39.539277 Longitude: -108.207040

CORRECTIVE ACTIONS:

1 CA# 144995

Corrective Action: Comply with Rule 1003.b and conduct reclamation on areas not needed for production and establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of pre-disturbance or reference area levels. Use a seed mixture requested by the surface owner, or a mixture prescribed by the local soil conservation district. Ensure erosion controls are implemented to stabilize the seeded soil, and continue to monitor and manage interim areas until Final Reclamation has passed. A CA date of 03/07/2016 is being provided as this is when Laramie took ownership of the Location.

Date: 03/01/2016

Response: CA COMPLETED

Date of Completion: 08/23/2021

Operator Comment: per inspection 696203089 issue addressed see attached inspection report

COGCC Decision: _____

COGCC Representative: _____

2 CA# 144996

Corrective Action: Comply with Rule 1002.f.(2) and install BMPs in accordance with good engineering practices. Temporary controls will be required by 1/9/2021 until interim reclamation of the Location is conducted, at which point long-term controls will need to be implemented.

Date: 01/09/2021

Response: CA COMPLETED

Date of Completion: 08/23/2021

Operator Comment: per inspection 696203089 issue addressed see attached inspection report

COGCC Decision: _____

COGCC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: _____

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Christina Pierce

Signed: _____

Title: Engineering Tech

Date: 8/30/2021 12:41:01 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

402796454	corrective action
-----------	-------------------

Total Attach: 1 Files