

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402731925

Date Received:  
06/28/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 46685

Name of Operator: KINDER MORGAN CO2 CO LP

Address: 1001 LOUISIANA ST SUITE 1000

City: HOUSTON State: TX Zip: 77002

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

General

CO2Source\_Regulatory@kindermorgan.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 693903328

Inspection Date: 06/17/2021

FIR Submit Date: 06/21/2021

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: KINDER MORGAN CO2 CO LP

Company Number: 46685

Address: 1001 LOUISIANA ST SUITE 1000

City: HOUSTON State: TX Zip: 77002

LOCATION - Location ID: 454998

Location Name: CB Number: 4 County: MONTEZUMA

Qtrqr: Lot 13 Sec: 10 Twp: 38N Range: 19W Meridian: N

Latitude: 37.561410 Longitude: -108.924790

FACILITY - API Number: 05-083-00 Facility ID: 454999

Facility Name: CB Number: 4

Qtrqr: Lot 13 Sec: 10 Twp: 38N Range: 19W Meridian: N

Latitude: 37.561410 Longitude: -108.924790

CORRECTIVE ACTIONS:

1 ☒ CA# 152041

Corrective Action:

Operator needs to reclaim the location or file for a delayed interim reclamation variance per the January 5 2017 notice to operators interim reclamation procedures for delayed operation, with the COGCC commission. Guidance on how to file with the commission can be obtained at the COGCC website in the "Hearings and Applications Process Guidebook". Corrective action date: 9/1/2021.

Date: 09/01/2021

Response: CA COMPLETED

Date of Completion: 12/15/2020

Kinder Morgan submitted an Interim Reclamation Variance Request via Form 4 (Document #402546285) on 12/15/20 for the CB-4 location. This variance request was prepared in accordance with the COGCC issued guidance titled "Notice to Operators: Interim Reclamation Procedures for Delayed Operations" dated January 5,

Operator Comment: 2017. COGCC did not process that variance request. It is our understanding that COGCC is requesting that operators who previously submitted variance requests that were not processed by COGCC follow soon-to-be-released guidance on requesting a hearing for variance requests. Kinder Morgan will follow that guidance once it is issued.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

2 ☒ CA# 152042

Corrective Action: Cover or install a functional wildlife escape ramp at the open cellar.

Date: 07/10/2021

Response: CA COMPLETED

Date of Completion: 06/28/2021

Operator Comment: The cellar has been filled with material thus preventing potential wildlife entrapment. The livestock panels around the cellar have been removed.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jenna Emerick

Signed: \_\_\_\_\_

Title: EHS Specialist

Date: 6/28/2021 4:24:50 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402731925	FIR RESOLUTION SUBMITTED
402731979	CB-4 Photo Log

Total Attach: 2 Files