

GOLDEN EAGLE MINE F-3 API# 05-071-06414 – OGRIS OPERATING
OGCC OPERATOR NUMBER 10758 - DATE: AUGUST 16, 2021
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695103298



PHOTO 1: THE LOCATION SIGN WAS MODIFIED TO INCLUDE THE CURRENT OPERATORS NAME, PHONE NUMBER AND EMERGENCY PHONE NUMBER.

GOLDEN EAGLE MINE F-3 API# 05-071-06414 – OGRIS OPERATING
OGCC OPERATOR NUMBER 10758 - DATE: SEPTEMBER 15, 2021
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695103298



PHOTO 2: THE RISER, POLYPIPE AND VALVE CAN WERE REMOVED FROM THE LOCATION. THE DISTURBED SOIL WAS SEEDED USING THE CPW APPROVED SEED MIX TO PROMOTE THE ESTABLISHMENT OF VEGETATION. THE EXISTING ROOT SYSTEM WAS NOT DISTURBED, VEGETATION SHOULD BEGIN TO EMERGE AFTER PRECIPITATION IS RECEIVED.

GOLDEN EAGLE MINE F-3 API# 05-071-06414 – OGRIS OPERATING LLC
OGCC OPERATOR NUMBER 10758 - DATE: OCTOBER 16, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695103298



PHOTO 3: THE DEBRE WAS REMOVED FROM THE LOCATION.