

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402814565

Date Received:  
09/16/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1675 BROADWAY, STE 2800  
City: DENVER State: CO Zip: 80202  
Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Victoria Dizghinjili</u>	<u>303-825-4822</u>	<u>vdizghinjili@kpk.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 697601550  
Inspection Date: 09/09/2021 FIR Submit Date: 09/09/2021 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: KP KAUFFMAN COMPANY INC Company Number: 46290  
Address: 1675 BROADWAY, STE 2800  
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 467175

Location Name: KPK Tank Battery Number: 28SWNE County: \_\_\_\_\_  
Qtrqr: SWNE Sec: 28 Twp: 2N Range: 67W Meridian: 6  
Latitude: 40.111493 Longitude: -104.891663

FACILITY - API Number: 05-123- -00 Facility ID: 467173

Facility Name: KPK Tank Battery Number: 28SWNE  
Qtrqr: SWNE Sec: 28 Twp: 2N Range: 67W Meridian: 6  
Latitude: 40.111493 Longitude: -104.891663

CORRECTIVE ACTIONS:

1 CA# 155667

Corrective Action: Control and contain spills/releases and clean up per Rule 912.a. by removing stained soil.

Date: 10/09/2021

Response: CA COMPLETED Date of Completion: 09/16/2021

Operator Comment: Stained soil at crude tank has been removed. Please see attached pictures.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

2 CA# 155668

Corrective Action: Control and contain spills/releases and clean up per Rule 912.a. by removing stained soil.

Date: 10/09/2021

Response: CA COMPLETED

Date of Completion: 09/16/2021

Operator Comment: Hydrocarbon stained soils under meter housing has been removed. Please see attached pictures.

COGCC Decision:

COGCC  
Representative:

3 CA# 155669

Corrective Action: Comply with Rule 606 by removing trash/debris from location

Date: 09/07/2021

Response: CA COMPLETED

Date of Completion: 09/16/2021

Operator Comment: Debris have been removed from location.

COGCC Decision:

COGCC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Victoria Dizghinjili

Signed:

Title: Engineering Tech

Date: 9/16/2021 3:31:35 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402814572	Stained soil removed PIC1
402814575	Stained soil removed PIC2

Total Attach: 2 Files