

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402786841

Date Received:
09/20/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10766
Name of Operator: ARKOMA OPERATIONS LLC
Address: 2121 S COLUMBIA AVE SUITE 101
City: TULSA State: OK Zip: 74114
Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Andrew Price</u>	<u>918-965-0044</u>	<u>aprice@arkomaops.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 693903556
Inspection Date: 08/12/2021 FIR Submit Date: 08/18/2021 FIR Status: _____

Inspected Operator Information:

Company Name: CATAMOUNT ENERGY PARTNERS LLC Company Number: 10464
Address: 1001 17TH STREET STE 1160
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 326237

Location Name: JQUES-N33N8W Number: 27NWSE County: LA PLATA
Qtrqr: NWSE Sec: 27 Twp: 33N Range: 8W Meridian: N
Latitude: 37.071771 Longitude: -107.700362

FACILITY - API Number: 05-067-00 Facility ID: 454845

Facility Name: Jaques Number: 12
Qtrqr: NWSE Sec: 27 Twp: 33N Range: 8W Meridian: N
Latitude: 37.071771 Longitude: -107.700362

CORRECTIVE ACTIONS:

1 CA# 154986

Corrective Action: -Debris was identified on the well pad and needs to be removed by 9/18/2021. Date: 09/18/2021

Response: CA COMPLETED Date of Completion: 09/17/2021

Operator Comment: Removed pieces of metal debris washed onto well pad.

COGCC Decision: _____

COGCC
Representative: _____

2 CA# 154987

Corrective Action: -Revegetation needs to be conducted within the interim reclamation areas (well pad cut and fill slopes).

Date: 11/12/2019

Response: CA COMPLETED

Date of Completion: 09/17/2021

Operator Comment: Mowed kochia on the fill slope.
We will reseed the cut and fill slopes before the 11/12/21 due date.

COGCC Decision: _____

COGCC
Representative: _____

3 CA# 154988

Corrective Action: -Stormwater and erosion controls need to be installed to stabilize erosion within the project area. Stormwater controls need to be selected, sized, installed, and maintained according to good engineering practices such as those described by CDOT in their erosion control manuals.

Date: 11/12/2019

Response: CA COMPLETED

Date of Completion: 09/17/2021

Operator Comment: Cleaned out diversion ditches, and removed sediment from the toe of the slope. Filled in rills and channels.
Rebuilt rock run down and cleaned out outlet piping.
Reseeded cut slope and diversion berms.

COGCC Decision: _____

COGCC
Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: _____

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jaime Pugh

Signed: _____

Title: Engineering Analyst

Date: 9/20/2021 1:58:59 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number Description

402816847	Jaques 6F,10,11,12 9-18-21 (693903556) remediation
-----------	--

Total Attach: 1 Files