

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/22/2021

Submitted Date:

09/22/2021

Document Number:

696303626

FIELD INSPECTION FORM

Loc ID 457475 Inspector Name: PETRIE, ERICA On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10661
Name of Operator: BISON OIL & GAS II LLC
Address: 518 17TH STREET #1800
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

2 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		ops@bisonog.com	
Kraich, Adam		adam.kraich@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
457476	WELL	DG	05/01/2021		123-47919	Hunt 8-60 17B-8-2	DG

General Comment:

Location

Overall Good:

Signs/Marker:			
Type	DRILLING/RECOMP		
Comment:	Workover Rig Sign NOT at First Point of Intersection of a Public Road and the Rig Access Road; See photos Location is over 3 Miles in from a Public Road. No Directional Sign Provided. (Main Lease Road has Multiple Leases, from Multiple Operators.)		
Corrective Action:	Install sign to comply with Rule 605.c.(1)-(3) Flowback/Completion directional sign not posted Workover Rig Sign not posted at Entrance from a Public Road	Date:	09/24/2021

Emergency Contact Number:			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: <input type="text"/>

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:			
Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected FacilitiesFacility ID: 457476 Type: WELL API Number: 123-47919 Status: DG Insp. Status: DG**Completion**Operation: Snubbing

Date Flowback:

Contractor:

Comment:

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Wednesday 09/22/2021 at approximately 16:08, I, Inspector Erica Petrie, conducted a Field Inspection at Bison Oil and Gas II, Hunt 8-60-17B, Location #457475 in Weld County, Colorado.</p> <p>While there, I observed Completion Operations</p> <p>During this Inspection the following possible compliance issues were observed:</p> <p>Workover Rig Sign NOT at First Point of Intersection of a Public Road and the Rig Access Road; See photos Location is over 3 Miles in from a Public Road. No Directional Signs Provided. (Main Lease Road has Multiple Leases, from Multiple Operators.) Install signs to comply with Rule 605.c.(1)-(3) Flowback/Completion directional signs not posted. Corrective Action date 09.24.2021</p>	petrie	09/22/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696303627	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5538068