

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/16/2021

Submitted Date:

09/16/2021

Document Number:

699503174

FIELD INSPECTION FORMLoc ID 320523 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10711

Name of Operator: PAINTED PEGASUS PETROLEUM LLC

Address: 16820 BARKER SPRINGS RD #521

City: HOUSTON State: TX Zip: 77084

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

5 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		jm@p3petro.com	
Gomez, Jason		jason.gomez@state.co.us	
Leonard, Mike		mike.leonard@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
276135	WELL	PR	01/01/2021	GW	001-09533	ABBOTT 10-43	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Deadman # & Marked

4

Comment:

Corrective Action:

Date:

Type: Plunger Lift

1

Comment:

Corrective Action:

Date:

Type: Bradenhead

1

Comment: Exposed to surface

Corrective Action:

Date:

Type: Ancillary equipment

1

Comment: Some automation equipment

Corrective Action:

Date:

Venting:

Yes/No NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 276135 Type: WELL API Number: 001-09533 Status: PR Insp. Status: PR

Idle WellPurpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____

Comment: All tubing has been removed except one joint used to install wellhead wraparound equipment.

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 06/18/2020 Annual Brhd Completed? _____

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: Bradenhead inaccessible or not visible 09/26/2021

Corrective Action: Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2) Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On 9/16/21 at approximately 1200 I, Inspector Justin Medina conducted an on-site inspection at:</p> <p>Well Name- Abbott 10-43</p> <p>Company Name- P3</p> <p>API- 05-001-09533</p> <p>In Adams County Colorado.</p> <p>While there, I observed TA well</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Bradenhead inaccessible or not visible</p> <p>Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2)</p> <p>9/26/21</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>Previous inspection corrective actions may still be valid.</p> <p>This is a summary of inspection report.</p>	medinaj	09/16/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
402814746	INSPECTION SUBMITTED	http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5533934
699503175	Inspection Pictures	http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5533929