

FORM
17
Rev
11/20

State of Colorado
Oil and Gas Conservation Commission



Document Number:

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109

BRADENHEAD TEST REPORT

Step 1. Before opening any valves, record all tubing and casing pressures as found.
Step 2. Collect liquid and gas samples as required; consult Bradenhead Testing and Reporting Instructions and Guidance for field specific Orders at <http://cogccreg.html#/opguidance>
Step 3. Conduct Bradenhead test.
Step 4. Submit Form 17 within 10 days of test. Attach a wellbore diagram if not previously submitted or if wellbore configuration has changed since last wellbore diagram was submitted.
Step 5. Submit sample analytical results via Form 43.

1. OGCC Operator Number: 10550 3. BLM Lease No: _____
2. Name of Operator: Mustang Resources, LLC
4. API Number; 05-045-06647 5. Multiple completion? Yes No
6. Well Name: DOWNING Number: 25-21-A-6S-94W
7. Location (QtrQtr, Sec, Twp, Rng, Meridian): NENW SEC25-T6S-R94W 6PM
8. County Garfield 9. Field Name: Rulison
10. Minerals: Fee State Federal Indian

11. Date of Test: 9-8-2021
12. Well Status: Flowing
 Shut In Gas Lift
 Pumping Injection
 Clock/Intermitter
 Plunger Lift
13. Number of Casing Strings:
 Two Three Liner?

14. EXISTING PRESSURES

Record all pressures as found	Tubing:	Tubing:	Prod Csg	Intermediate	Surf. Csg
	Fm: <u>25</u>	Fm: _____	Fm: <u>25</u>	Csg: _____	<u>Q</u>

BRADENHEAD TEST

With gauges monitoring production, intermediate casing and tubing pressures, open surface casing (Bradenhead) valve (if no intermediate casing, monitor only the production casing and tubing pressures.) Record pressures at five minute intervals.
Describe character of flow in "Bradenhead Flow" column: O = No Flow; C = Continuous; D = Down to 0; S = Surge; W = Whisper
Describe fluid type in "Bradenhead Fluid" column: H = Water H2O; M = Mud; G = Gas; V = Vapor; L = Liquid Hydrocarbon; H & M = Water & Mud; H & G = Water & Gas; H & V = Water & Vapor; M & G = Mud & Gas; M & V = Mud & Vapor; G & V = Gas & Vapor; H & L = Water & Liquid Hydrocarbon; M & L = Mud & Liquid Hydrocarbon; G & L = Gas & Liquid Hydrocarbon; V & L = Vapor & Liquid Hydrocarbon; N = None

Buried valve? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No Confirmed open? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	BRADENHEAD SAMPLE TAKEN? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Gas <input type="checkbox"/> Liquid	Character of Bradenhead fluid: <input type="checkbox"/> Clear <input type="checkbox"/> Fresh <input type="checkbox"/> Sulfur <input type="checkbox"/> Salty <input type="checkbox"/> Black Other:(describe) <u>None</u>	Elapsed Time (Min:Sec)	Fm: Tubing	Fm: Tubing:	Prod Csg PSIG	Intermedia Csg PSIG	Bradenhead Flow:	Bradenhead Fluid:
			5:00	<input type="checkbox"/> 25	<input type="checkbox"/>	<input type="checkbox"/> 25		<u>Q</u>	<u>Q</u>
10:00	<input type="checkbox"/> 25	<input type="checkbox"/>	<input type="checkbox"/> 25		<u>Q</u>	<u>Q</u>			
15:00	<input type="checkbox"/> 25	<input type="checkbox"/>	<input type="checkbox"/> 25		<u>Q</u>	<u>Q</u>			
20:00	<input type="checkbox"/> 25	<input type="checkbox"/>	<input type="checkbox"/> 25		<u>Q</u>	<u>Q</u>			
25:00	<input type="checkbox"/> 25	<input type="checkbox"/>	<input type="checkbox"/> 25		<u>Q</u>	<u>Q</u>			
30:00	<input type="checkbox"/> 25	<input type="checkbox"/>	<input type="checkbox"/> 25		<u>Q</u>	<u>Q</u>			
Instantaneous Bradenhead PSIG at end of test: > <u>Q</u>									

INTERMEDIATE CASING TEST

With gauges monitoring production, intermediate casing and tubing pressures, open the intermediate casing valve. Record pressures at five minute intervals.

Describe character of flow in "Intermediate Flow" column: O = No Flow; C = Continuous; D = Down to 0; S = Surge; W = Whisper
 Describe fluid type in "Intermediate Fluid" column: H = Water H₂O; M = Mud; G = Gas; V = Vapor; L = Liquid Hydrocarbon; H & M = Water & Mud; H & G = Water & Gas; H & V = Water & Vapor; M & G = Mud & Gas; M & V = Mud & Vapor; G & V = Gas & Vapor; H & L = Water & Liquid Hydrocarbon; M & L = Mud & Liquid Hydrocarbon; G & L = Gas & Liquid Hydrocarbon; V & L = Vapor & Liquid Hydrocarbon; N = None.

	Elapsed Time (Min:Sec)	Fm: Tubing	Fm: Tubing:	Prod Csg PSIG	Intermediate Csg PSIG	Intermediate Flow:	Intermediate Fluid:
Buried valve? <input type="checkbox"/> Yes <input type="checkbox"/> No							
Confirmed open? <input type="checkbox"/> Yes <input type="checkbox"/> No							
INTERMEDIATE SAMPLE TAKEN? <input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Gas <input type="checkbox"/> Liquid							
Character of Intermediate fluid: <input type="checkbox"/> Clear <input type="checkbox"/> Fresh <input type="checkbox"/> Sulfur <input type="checkbox"/> Salty <input type="checkbox"/> Black Other:(describe) <u> </u>							
Instantaneous Intermediate Casing PSIG at end of test: > _____							

Comments: No intermediate casing.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Test Performed By: Doug Wagoner Title: Field operator Phone: 0970-326-3141
 Signed: Doug Wagoner Title: _____ Date: 9-8-2021
 Witnessed By: _____ Title: _____ Agency: _____