

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402102594

Date Received:

02/11/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-3779

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Luke Reddy

970-515-1292

luke.reddy@anadarko.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 674902665

Inspection Date: 03/12/2019

FIR Submit Date: 03/21/2019

FIR Status: _____

Inspected Operator Information:

Company Name: KERR MCGEE OIL & GAS ONSHORE LP

Company Number: 47120

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-3779

LOCATION - Location ID: 327691

Location Name: UPRR 43 PAN AM S-61N68W Number: 11SESE County: _____

Qtrqr: SESE Sec: 11 Twp: 1N Range: 68W Meridian: 6

Latitude: 40.062040 Longitude: -104.964750

FACILITY - API Number: 05-123- -00 Facility ID: 327691

Facility Name: UPRR 43 PAN AM S-61N68W Number: 11SESE

Qtrqr: SESE Sec: 11 Twp: 1N Range: 68W Meridian: 6

Latitude: 40.062040 Longitude: -104.964750

CORRECTIVE ACTIONS:

1 ☒ CA# 123405

Corrective Action: Perform reclamation in accordance to Rule 1004. Remove gravel and culvert from the access road; perform compaction alleviation and re-contour/re-grade. Remove remaining debris. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Ensure erosion controls are implemented to stabilize the seeded soil. Operator shall continue to monitor and manage this site until the location meets Rule 1004 standards. Operator is directed to perform corrective actions outlined on this inspection report immediately. Doing so may decrease the duration of the alleged violations and the penalties that may be assessed pursuant to Rule 523.

Date: 03/24/2016

Response: CA COMPLETED

Date of Completion: 10/22/2019

Operator Comment: Reclamation variance, doc #402101734, was submitted 7/10/2019.
Location was mowed, slot trenches filled in, Graded to Re-countour, Ripped, Import Compost, Disk, Drill Dryland Pasture Mix, Spread Straw, Crimp to stabilize on 10/22/2019.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

2 ☒ CA# 123406

Corrective Action: Complete erosion repairs. Install or repair required BMPs per Rule 1002.f. in accordance with good engineering practices.

Date: 03/12/2019

Response: CA COMPLETED

Date of Completion: 10/22/2019

Operator Comment: Reclamation variance, doc #402101734, was submitted 7/10/2019.
Location was mowed, slot trenches filled in, Graded to Re-countour, Ripped, Import Compost, Disk, Drill Dryland Pasture Mix, Spread Straw, Crimp to stabilize on 10/22/2019.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Reclamation variance, doc #402101734, was submitted 7/10/2019.
Location was mowed, slot trenches filled in, Graded to Re-countour, Ripped, Import Compost, Disk, Drill Dryland Pasture Mix, Spread Straw, Crimp to stabilize on 10/22/2019.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Luke Reddy

Signed: _____

Title: Regulatory Specialist

Date: 2/11/2020 11:13:48 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402102594	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files