

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/21/2021

Submitted Date:

09/21/2021

Document Number:

699803649

FIELD INSPECTION FORMLoc ID 334880 Inspector Name: De Paolo, Corey On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: PO BOX 370

City: PARACHUTE State: CO Zip: 81635

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

14 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211288	WELL	PR	12/05/1996	GW	045-07047	UNOCAL GM 14-2	PR
270907	WELL	PR	12/24/2003	GW	045-09801	AMERICAN SODA GM 514-2	PR
271037	WELL	PR	05/31/2004	GW	045-09800	AMERICAN SODA GM 414-2	PR

General Comment:**COGCC Inspection Report Summary**

On Tuesday 9/21/21 at approximately 12:30 hours, I, Inspector Corey De Paolo, Conducted an on-site inspection at TEP ROCKY MOUNTAIN LLC UNOCAL-67S96W /2SWSW, Location #334880 in Garfield County Colorado.

While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1) Horizontal separators includes glycol storage tank. Glycol storage tank is approximately 2'x3'x10' with an approximate capacity of 11 barrels. Glycol storage tank missing required information with a corrective action date of 12/21/21.

A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Horizontal separator includes glycol storage tanks. Glycol storage tanks is approximately 2'x3'x10' with an approximate capacity of 11 barrels. Glycol storage tank missing required information.		
Corrective Action:	All Tanks with a capacity of 10 Barrels or greater will be labeled with Name of operator, Operator's emergency contact telephone number, Tank capacity, Tank contents, and NFPA label or equivalent globally harmonized label.	Date:	12/21/2021
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/970-285-9377

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Horizontal Heated Separator	# 4		
Comment:			

Corrective Action:		Date:	
Type: Plunger Lift	# 3		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 3		
Comment:	All meter runs have been calibrated in the last year.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Chemical tank		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	300 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
			Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			
		Date:	

Flaring:

Type			
Comment:			
Corrective Action:			
		Date:	

Inspected FacilitiesFacility ID: 211288 Type: WELL API Number: 045-07047 Status: PR Insp. Status: PR**Producing Well**Comment: Producing

Corrective Action:

Date:

Facility ID: 270907 Type: WELL API Number: 045-09801 Status: PR Insp. Status: PR**Producing Well**Comment: Producing

Corrective Action:

Date:

Facility ID: 271037 Type: WELL API Number: 045-09800 Status: PR Insp. Status: PR**Producing Well**Comment: Producing

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
		Culverts				
Ditches						
		Berms				
Compaction						
Sediment Traps						
		Ditches				
Gravel						
		Gravel				
		Gravel				
		Compaction				
		Sediment Traps				

Comment: Location appears to have some gravel throughout the location with light compaction. Places with light to no gravel are present on location. Light gravel and light compaction could lead to future stabilization and tracking issues.

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Refer to Sign/Markers for corrective actions.	depaoloc	09/21/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699803650	Photos for Insp. #699803649	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5539355