

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/15/2021

Submitted Date:

09/21/2021

Document Number:

694500369

## FIELD INSPECTION FORM

 Loc ID 316764 Inspector Name: NEIDEL, KRIS On-Site Inspection  2A Doc Num: \_\_\_\_\_
**Operator Information:**
 OGCC Operator Number: 6720  
 Name of Operator: ROBERT L BAYLESS PRODUCER LLC  
 Address: 621 17TH ST STE 2300  
 City: DENVER State: CO Zip: 80293
**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 3 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
thomas, john	505-326-2659	jthomas@rlbayless.com	
Trujillo, Helen		htrujillo@rlbayless.com	
Fischer, Alex		alex.fischer@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
232726	WELL	PR	02/01/2021	OW	107-06140	DRY CREEK FEDERAL 1-14	EI

**General Comment:**

**Inspected Facilities**

Facility ID: 232726 Type: WELL API Number: 107-06140 Status: PR Insp. Status: EI

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

Type: Flare                      Lined: NO                      Pit ID: 480784                      Lat:                      Long:

Reference Point: \_\_\_\_\_                      Other: \_\_\_\_\_                      Length: \_\_\_\_\_                      Width: \_\_\_\_\_

**Lining:**

Liner Type:    Liner Condition:

Comment: Pit is not currently in use, it is being closed. Pit ID was created by COGCC staff. At time of inspection, it was apparent that impact remains in soil after initial excavation. Groundwater appears to be shallow in the area.

Corrective Action: within 21 days of receiving sample results of soil sampling, submit on a supplemental Form 27.

Date: 11/30/2021

**Fencing:**

Fencing Type: Safety    Fencing Condition: Inadequate

Comment: fence was removed to allow work on pit

Corrective Action: prevent wildlife from entering pit.

Date:

**Netting:**

Netting Type:    Netting Condition:

Comment: no netting

Corrective Action:

Date:

Anchor Trench Present:                      Oil Accumulation:                      2+ feet Freeboard:

Comment:

Corrective Action:

Date:

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402818599	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5536791">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5536791</a>
694500370	photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5536766">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5536766</a>