

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/24/2021

Submitted Date:

09/28/2021

Document Number:

696203162

FIELD INSPECTION FORM

Loc ID 324459 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10515

Name of Operator: GUNNISON ENERGY LLC

Address: 1801 BROADWAY #1150

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

6 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		heather.lang@oxbow.com	
		tyson.johnston@oxbow.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
324459	LOCATION	AC			-	FEDERAL-610S90W 32SWSE	RI

General Comment:

On 9/24/2021, Reclamation Specialist Trujillo conducted an interim reclamation and stormwater inspection at Gunnison Energy's Federal 10-90-32 location in Gunnison County, Colorado.

The following compliance issues were observed during this inspection:
 606.a: EQUIPMENT, WEEDS, WASTE, AND TRASH REQUIREMENTS.
 912: Stained Soils
 1002.f: Pad stabilization
 1003/1002.e: Interim Reclamation and Surface Disturbance Minimization

Refer to the "Location", "Reclamation" and "Stormwater" sections of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up inspection on this site will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

LocationOverall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	STORAGE OF SUPL		
Comment:	Trailer equipment/Equipment not necessary for production observed stored on the Location.		
Corrective Action:	Comply with Rule 606	Date:	10/13/2021

Overall Good: ☐**Spills:**

Type	Area	Volume		
		<= 1 bbl		
Comment:	Stained soils observed on production area, southwest of the well.			
Corrective Action:	Clean up impacted soils per Rule 912.a. and remediate to Table 915-1 Cleanup Concentrations; for non-E&P waste comply with Rules 906.a-d			Date: 10/28/2021

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____ Fail _____

Comment _____

Trailers observed stored on the interim areas of the Location, and vehicle rutting observed on off-site areas of the Location; this does not comport with Rule 1002.e; See "Good Housekeeping" and the "Interim Reclamation" sections of this report.

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment Various vehicle travel and storage of trailers on the interim and off-site areas of the Location has resulted in additional degradation and disturbance. Areas require reclamation.

Corrective Action Comply with 1003 Rules

Date 11/15/2021

Overall Interim Reclamation Fail

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment:

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment:

Corrective Action:

Date _____

Overall Final Reclamation _____

Well Release on Active Location ☐

Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Control measures to stabilize the production area missing or insufficient; vehicle rutting, tracking and degradation evident on pad and location entrance.](#)

Corrective Action: [Comply with Rule 1002.f](#)

Date: 10/05/2021

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696203163	Location Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5542221