

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

09/22/2021

Submitted Date:

09/22/2021

Document Number:

696303626

FIELD INSPECTION FORM
 Loc ID 457475 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 10661

Name of Operator: BISON OIL & GAS II LLC

Address: 518 17TH STREET #1800

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

2 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Kraich, Adam		adam.kraich@state.co.us	
,		ops@bisonog.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
457476	WELL	DG	05/01/2021		123-47919	Hunt 8-60 17B-8-2	DG

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	DRILLING/RECOMP		
Comment:	Workover Rig Sign NOT at First Point of Intersection of a Public Road and the Rig Access Road; See photos Location is over 3 Miles in from a Public Road. No Directional Sign Provided. (Main Lease Road has Multiple Leases, from Multiple Operators.)		
Corrective Action:	Install sign to comply with Rule 605.c.(1)-(3) Flowback/Completion directional sign not posted Workover Rig Sign not posted at Entrance from a Public Road	Date:	09/24/2021

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 457476 Type: WELL API Number: 123-47919 Status: DG Insp. Status: DG**Completion**Operation: Snubbing

Date Flowback:

Contractor:

Comment:

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Wednesday 09/22/2021 at approximately 16:08, I, Inspector Erica Petrie, conducted a Field Inspection at Bison Oil and Gas II, Hunt 8-60-17B, Location #457475 in Weld County, Colorado.</p> <p>While there, I observed Completion Operations</p> <p>During this Inspection the following possible compliance issues were observed:</p> <p>Workover Rig Sign NOT at First Point of Intersection of a Public Road and the Rig Access Road; See photos</p> <p>Location is over 3 Miles in from a Public Road. No Directional Signs Provided. (Main Lease Road has Multiple Leases, from Multiple Operators.) Install signs to comply with Rule 605.c.(1)-(3) Flowback/Completion directional signs not posted. Corrective Action date 09.24.2021</p>	petrie	09/22/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402820082	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5538070
696303627	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5538068