

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/22/2021

Submitted Date:

09/22/2021

Document Number:

696303628

**FIELD INSPECTION FORM**Loc ID 457131 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10661

Name of Operator: BISON OIL &amp; GAS II LLC

Address: 518 17TH STREET #1800

City: DENVER State: CO Zip: 80202

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

2 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kraich, Adam		adam.kraich@state.co.us	
,		ops@bisonog.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
457132	WELL	PR	02/22/2019	OW	123-47779	Hunt 8-60 17A-8-2	PR

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	DRILLING/RECOMP		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Workover Rig Sign NOT at First Point of Intersection of a Public Road and the Rig Access Road; See photos  
Location is over 2.5 Miles in from a Public Road. No Directional Sign Provided. (Main Lease Road has Multiple Leases, from Multiple Operators.)

Corrective Action: Install sign to comply with Rule 605.c.(1)-(3)  
Flowback/Completion directional sign not posted.  
Workover Rig Sign not posted at Entrance from a Public Road

Date: 09/24/2021

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 457132 Type: WELL API Number: 123-47779 Status: PR Insp. Status: PR

**COGCC Comments**

Comment	User	Date
<p><a href="#">COGCC Inspection Report Summary</a></p> <p>On Wednesday 09/22/2021 at approximately 16:20, I, Inspector Erica Petrie, conducted a Field Inspection at Bison Oil and Gas II, Hunt 8-60 17A PAD Location #457131 in Weld County, Colorado.</p> <p>While there, I observed Completion Operations</p> <p>During this Inspection the following possible compliance issues were observed:</p> <p>Workover Rig Sign NOT at First Point of Intersection of a Public Road and the Rig Access Road; See photos</p> <p>Location is over 2.5 Miles in from a Public Road. No Directional Signs Provided. (Main Lease Road has Multiple Leases, from Multiple Operators.) Install signs to comply with Rule 605.c. (1)-(3) Flowback/Completion Directional Signs not posted. Corrective Action date 09.24.2021</p>	petrie	09/22/2021

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402820083	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5538071">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5538071</a>
696303629	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5538069">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5538069</a>