

**FORM  
INSP**Rev  
X/20

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

10/01/2021

Submitted Date:

10/05/2021

Document Number:

693700879

**FIELD INSPECTION FORM**
 Loc ID 444471 Inspector Name: ALLISON, RICK On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 96155

Name of Operator: WHITING OIL &amp; GAS CORPORATION

Address: 1700 LINCOLN STREET SUITE 4700

City: DENVER State: CO Zip: 80290

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

2 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
CO, Eastern		WhitingEasternCO@Whiting.com	<a href="#">All Eastern CO Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
480257	SPILL OR RELEASE	AC	07/19/2021		-	Razor 25P	EI
480867	SPILL OR RELEASE	AC	10/04/2021		-	Razor 25P	EI

**General Comment:**

Inspected Facilities							
Facility ID:	480257	Type:	SPILL OR	API Number:	-	Status: AC	Insp. Status: EI
Facility ID:	480867	Type:	SPILL OR	API Number:	-	Status: AC	Insp. Status: EI

**Environmental****Spill/Remediation:**

Comment:	COGCC Inspection of Spill 480257 reported 7/5/2021. Excavation remains open at Spill location. COGCC observed evidence of a recent release on flowline during inspection and notified Operator via phone. Operator subsequently reported Spill 480867. Rule 912.b.(6) requires closure of Spill within 90 days or submittal of a Form 27 Site Investigation and Remediation Workplan.	
Corrective Action:	Submit form 19 Supplemental with root cause/correction action for Spill and soil sample data supporting a closure request, or submit a Form 27 with proposal and timeline for further investigation and remediation.	Date: 10/03/2021

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402832412	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5547950">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5547950</a>
693700880	Recent flowline release.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5547949">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5547949</a>