

# Inspection Photos

API: 071-06491

API: 071-06735

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 10/8/2021



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06491 | Date: 10/8/2021

## Inspection Photos



**Photo 1.** Facing south at the access road near the county road, red arrow points to the access gate. There is vehicle rutting in this area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06491 | Date: 10/8/2021

## Inspection Photos



**Photo 2.** There is vehicle tracks that backed up from the gate and drove off the access road toward the county road. Landowner put up the t-post and rope since the unauthorized access took place. All oil and gas vehicles must stay within access road boundary. Lat/Long:37.230458,-104.69600



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06491 | Date: 10/8/2021

## Inspection Photos



**Photo 3.** The vehicle tracks across the landowners property need to be raked out and repaired.



**Photo 4.** This photo was provided by the surface owner showing the Evergreen vehicle that had driven down the road the day the vehicle had driven off the road across the landowners property.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06491 | Date: 10/8/2021

## Inspection Photos



**Photo 5.** Facing southwest further uphill along the access road. There are erosion issues along the road and the culvert show at red arrow is filled in with sediment.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06491 | Date: 10/8/2021

## Inspection Photos



**Photo 6.** Stormwater erosion is occurring down the road shown at red arrow.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06491 | Date: 10/8/2021

## Inspection Photos



**Photo 7.** There are multiple culverts further along the road that are filled in with sediment that need maintenance.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06491 | Date: 10/8/2021

## Inspection Photos



**Photo 8.** Facing northeast along the road near the top of the ridge.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06491 | Date: 10/8/2021

## Inspection Photos



**Photo 9.** Facing north along the access road. There is vehicle rutting occurring in this area and stormwater is not be properly diverted.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06491 | Date: 10/8/2021

## Inspection Photos



**Photo 10.** Facing northwest at the well site. Stormwater is not properly diverted in this area of the road causing water pooling on the road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06491 | Date: 10/8/2021

## Inspection Photos



**Photo 11.** Facing north toward the [LEFT FIELD #31-29](#) well site.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06491 | Date: 10/8/2021

## Inspection Photos



**Photo 12.** There appears to be drilling mud in the pit that needs to be cleaned up.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06491 | Date: 10/8/2021

## Inspection Photos



**Photo 13.** Facing southeast toward the LEFT FIELD #31-29 TR well site.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06491 | Date: 10/8/2021

## Inspection Photos



**Photo 14.** There is oily rags found in the engine skid.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06491 | Date: 10/8/2021

## Inspection Photos



**Photo 15.** There appears to be drilling mud in the pit that needs to be cleaned up.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06491 | Date: 10/8/2021