

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/11/2021

Submitted Date:

10/11/2021

Document Number:

695104929

FIELD INSPECTION FORM

Loc ID 333490 Inspector Name: Beardslee, Tom On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10672
Name of Operator: TIMBER CREEK OPERATING LLC
Address: 6295 GREENWOOD PLAZA BLVD #100
City: GREENWOOD State: CO Zip: 8111-

Findings:

- 9 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Fitzgerald, Edie	719-859-1394	efitzgerald@ogrisop.com	All Inspections
GEE, GREG	903-987-0353	ggee@ogrisop.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
279158	WELL	PR	01/05/2006	GW	071-08473	HILL RANCH 16-09	PR
290491	WELL	PR	01/01/2018	GW	071-09275	HILL RANCH 16-09VX	PR

General Comment:

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

OTHER

Comment:

PHOTO 3: AREA OF IMPACTED SOIL APPEARS TO BE OILY WASTE FROM PROME MOVER ENGINE SKID.

Corrective Action:

Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002.(2).D.

Date: 10/18/2021

Overall Good:

Spills:

Type

Area

Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type PIT

Comment:

ELECTRIC FENCE CA FROM PREVIOUS INSPECTION HAS BEEN ADDRESSED.

Corrective Action:

Date:

Equipment:

corrective date

Type: Ancillary equipment

2

Comment:

TELEMETRY EQUIPMENT

Corrective Action:

Date:

Type: Progressive Cavity

1

Comment:

Corrective Action:

Date:

Type: Prime Mover

1

Comment:

Corrective Action:

Date:

Type: Gas Meter Run

2

Comment:

BOTH CAL. REPORTS INDICATE GAS METERS HAVE BEEN CALIBRATED WITHIN THE LAST YEAR.

Corrective Action:

Date:

Type: Vertical Separator

2

Comment:

Corrective Action:

Date:

Type: Bradenhead

2

Comment:

BOTH ARE PLUMBED TO SURFACE

Corrective Action:		Date:	
--------------------	--	-------	--

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 279158 Type: WELL API Number: 071-08473 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

Facility ID: 290491 Type: WELL API Number: 071-09275 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: YES Pit ID: 292545 Lat: 36.995300 Long: -104.886300

Reference Point: SE Other: _____ Length: 100 Width: 100

Lining:

Liner Type: _____ Liner Condition: Adequate

Comment:

Corrective

Date: _____

Fencing:

Fencing Type: Wildlife Fencing Condition: Adequate

Comment:

Corrective

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment: NONE

Corrective

Date: _____

Anchor Trench Present: YES Oil Accumulation: NO 2+ feet Freeboard: YES

Comment:

Corrective

Date: _____

COGCC Comments

Comment	User	Date
<u>THIS IS A FOLLOW UP TO INSP. DOC #690200882, CA'S HAVE BEEN ADDRESSED.</u>	beardslt	10/11/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402841280	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5554615
695104930	INSP. PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5554598