

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/30/2021

Submitted Date:

10/15/2021

Document Number:

700900792**FIELD INSPECTION FORM**Loc ID 319912 Inspector Name: Finkenbinder, Chane On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 31257Name of Operator: FRITZLER RESOURCES INCAddress: P O BOX 114City: FORT MORGAN State: CO Zip: 80701**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|----------------|----------------|-----------------------|---------------------------------|
| Fritzler, Gene | (970) 867-9388 | gfritzler@bresnan.net | All Inspections |

General Comment:

Location

| | | | |
|--------------------|--|-------|------------|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Access roads not accessible or maintained to get to well | | |
| Corrective Action | Location is within a designated setback location, maintain and repair access roads per Rule 204. Corrective Action Date 11/12/2021. See attached photo #1. | Date: | 11/12/2021 |

Overall Good: ☐

Emergency Contact Number:

| | | | |
|--------------------|--|-------|--|
| Comment: | | | |
| Corrective Action: | | | |
| | | Date: | |

Overall Good: ☐

| | | | | |
|----------------|------|--------|--|--|
| Spills: | | | | |
| Type | Area | Volume | | |

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

| | | | |
|--------------------|--|-------|--|
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

COGCC Comments

| Comment | User | Date |
|--|----------|------------|
| <p>COGCC Inspection Report Summary</p> <p>On Thursday September 30, 2021. at approximately 12:00pm. I, Inspector Chane Finkenbinder, conducted an on-site inspection at Simpson A8, Fritzler Oil, at API #001-07274 in Adams County Colorado.</p> <p>While there, I observed a temperately abandoned well.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Access roads not accessible or maintained to get to well. Location is within a designated setback location, maintain and repair access roads per Rule 204. Corrective Action Date 11/12/2021. See attached photo #1.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p> | finkenbc | 10/15/2021 |

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|------------------|---|
| 700900793 | Inspection photo | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5565036 |