

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	OTHER		
Comment:	ancillary equip. has fabricated steel pipe and round stock		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	fabricated angle iron		
Corrective Action:		Date:	

Equipment:

Type		#	corrective date
Bradenhead		# 1	
Comment:	appears to be plumbed to surface		
Corrective Action:		Date:	
Prime Mover		# 1	
Comment:	electric motor		
Corrective Action:		Date:	
Ancillary equipment		# 1	
Comment:	electric panel, meter box and transformers		
Corrective Action:		Date:	
Pump Jack		# 1	
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 241173 Type: WELL API Number: 123-08961 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 09/24/2020 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: Submit test results to the COGCC

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Wednesday 10/27/2021 at approximately 1430 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a KP Kauffman location: Follow up inspection to Doc # 699304052. Sidney Strear #3 at Location #318364 in Weld County Colorado. While there, I observed a wellsite, PR at the time of inspection. During this inspection the following possible compliance issue has been addressed: 1002..(2).D Housekeeping: Stained soil around WH has been cleaned up. See attached photos. Location: dry, Weather: cloudy. No follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report</p>	revasr	10/27/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699304431	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5565768