

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/26/2021

Submitted Date:

10/26/2021

Document Number:

697004748

FIELD INSPECTION FORMLoc ID 446471 Inspector Name: Peterson, Tom On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

6 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
446600	TANK BATTERY	AC	07/15/2016		-	EDKAM 3-28	AO

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Calibration card is current.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	FIBERGLASS AST		,
Comment:	50 bbls. Produced water tank is anchored.				
Corrective Action:				Date:	

Paint

Condition Adequate

Other (Content)

Other (Capacity)

Other (Type)

Berms

Inspector Name: Peterson, Tom

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Inadequate	Walls Sufficent	Base Sufficent	Inadequate	
Comment:	Secondary containment is inadequate to contain 150% of the volume of the largest tank. See attached photo.				
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 603.o.				Date: 12/31/2021

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	2	300 BBLS	STEEL AST		,	
Comment:	Crude oil tanks are anchored.					
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Inadequate	Walls Sufficent	Base Sufficent	Inadequate	
Comment:	Secondary containment is inadequate to contain 150% of the volume of the largest tank. See attached photo.				
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 603.o.				Date: 12/31/2021

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Tuesday 10/26/2021 at approximately 13:35 hours, I, Inspector Tom Peterson, conducted an on-site inspection at the KPK Edkam 3-28 Tank Battery location #446600 in Weld County, Colorado.</p> <p>While there, I observed that the crude oil and produced water tanks had insufficient berms. During this inspection the following possible compliance issues were observed: Rule 603.o. with a corrective action date of 12/31/2021.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of the inspection report.</p>	petersont	10/26/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402853768	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5564567
697004749	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5564563