

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402863129

Date Received:

11/05/2021

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10758

Name of Operator: OGRIS OPERATING LLC

Address: PO BOX 53467

City: MIDLAND State: TX Zip: 79710

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Gee, Greg

Phone

903-987-0353

Email

ggee@ogrisop.com

efitzgerald@ogrisop.com

timothy.thomsen@state.co.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 690201754

Inspection Date: 07/07/2021

FIR Submit Date: 07/08/2021

FIR Status: _____

Inspected Operator Information:

Company Name: TIMBER CREEK OPERATING LLC

Company Number: 10672

Address: 6295 GREENWOOD PLAZA BLVD #100

City: GREENWOOD State: CO Zip: 8111-4978
VILLAGE

LOCATION - Location ID: 308989

Location Name: APACHE CANYON-634S67W Number: 19SESW County: LAS ANIMAS

Qtrqtr: SESW Sec: 19 Twp: 34S Range: 67W Meridian: 6

Latitude: 37.064246 Longitude: -104.929947

FACILITY - API Number: 05-071- -00 Facility ID: 286229

Facility Name: APACHE CANYON Number: 19-14

Qtrqtr: SESW Sec: 19 Twp: 34S Range: 67W Meridian: 6

Latitude: 37.064246 Longitude: -104.929947

CORRECTIVE ACTIONS:

1 CA# 152512

Corrective Action: Maintain in good mechanical condition per Rule 608.e.

Date: 07/30/2021

Response: CA COMPLETED

Date of Completion: 09/09/2021

Operator
Comment:

THE SOUND WALL PANEL THAT WAS ON THE GROUND WAS PLACED BACK INTO POSITION.

COGCC Decision: _____

COGCC
Representative:

2 CA# 152513

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 07/30/2021

Response: CA COMPLETED

Date of Completion: 10/22/2021

Operator
Comment:

THE ROAD SURFACE WAS CROWNED TO CREATE SHEET FLOW AND ELIMINATE THE TIRE RUTS. ADDITIONAL GRAVEL WAS INSTALLED TO THE ROADWAY SURFACE TO PROVIDE STABILIZATION. COMPLETED ON 10/22/2021. EROSION CONTROL BLANKETS WERE INSTALLED ON THE WELL PAD CUT SLOPE FOR EROSION CONTROL, THIS WAS COMPLETED ON 11/04/2021. SEE ATTACHED PHOTO LOG FOR DETAILS.

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: ALL CORRECTIVE ACTIONS HAVE BEEN ADDRESSED.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Edie Fitzgerald

Signed: _____

Title: Sr. Environmental Tech.

Date: 11/5/2021 9:05:42 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402863138	PHOTO LOG
-----------	-----------

Total Attach: 1 Files