

TEP
RGU 34-19-198
Location # 316474



Location/signage illegible



location

TEP
RGU 34-19-198
Location # 316474



Load out lines missing caps/bull plugs



Load out lines missing caps/bull plugs



TEP
RGU 34-19-198
Location # 316474



Lack of stabilization/erosion



Lack of stabilization/erosion

TEP
RGU 34-19-198
Location # 316474



Lack of stabilization/erosion



Lack of stabilization/erosion/sediment migration