

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

11/15/2021

Submitted Date:

11/15/2021

Document Number:

693505819**FIELD INSPECTION FORM**
 Loc ID 318223 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
,	303-825-4822	cogcc@kpk.com	All Inspections
Watzman, Ross	(303) 825-4822	rwatzman@kpk.com	all inspections.

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240911	WELL	PR	03/20/1995	OW	123-08699	DORIS ACKERSON UNIT 2	PR

General Comment:[Re-inspection per Doc# 693505230](#)

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign not legible		
Corrective Action:	Install sign to comply with Rule 605.g.	Date:	07/17/2021

Emergency Contact Number:

Comment:		Date: _____
Corrective Action:		

Good Housekeeping:

Type	OTHER		
Comment:	Dead weeds around location and around electric panel.		
Corrective Action:	Comply with rule 606	Date:	07/17/2021

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 240911 Type: WELL API Number: 123-08699 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 10/28/2021 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: -- Fluid Type: End Surf Csg Pressure: --

Comment:

Corrective Action:

Date:

COGCC Comments

Comment

User

Date

COGCC Inspection Report Summary On Wednesday November 15, 2021, at approximately 11:17AM, I, Inspector Randy Silver, conducted an on-site re-inspection Per doc#693505230. Location: Doris Ackerson #2 Operator: KP Kauffman API#:123-08699 County: Weld While there, I observed a producing well site. During this inspection the following possible compliance issues were observed: Well sign: Rule 605 g Corrective action date of 7-17-21 see photos 1,2 Weeds: Rule 606 Corrective action date of 7-17-21. At time of inspection it does not appear that corrective actions for previous inspection have been addressed. Weather conditions: Dry and hot A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

silverr

11/15/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693505820	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5581509