

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/15/2021

Submitted Date:

11/15/2021

Document Number:

693505825**FIELD INSPECTION FORM**Loc ID 317765 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**9 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Watzman, Ross	(303) 825-4822	rwatzman@kpk.com	all inspections.
,	303-825-4822	cogcc@kpk.com	All Inspections
Adamczyk, Megan		megan.adamczyk@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
239943	WELL	PR	03/20/1995	OW	123-07731	A L LUFT 1	PR

General Comment:[Inspection due to complaint Soc#402865422](#)

Location

Lease Road:			
Type	Access		
comment:	Access: Bridge over irregation ditch, Bridge decking is rotting and needs to be addressed.		
Corrective Action	Comply with 600 rules.	Date:	12/15/2021

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	electric panel		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 239943 Type: WELL API Number: 123-07731 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 10/19/2021 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: -- Fluid Type: End Surf Csg Pressure: --

Comment:

Corrective Action:

Date:

COGCC Comments

Comment

User

Date

COGCC Inspection Report Summary
 On Monday November 15, 2021 at approximately 3:04PM, I, Inspector Randy Silver, conducted an on-site inspection.
 Location: AL Luft #1
 Operator: KP Kauffman
 API#:123-07731
 County: Weld
 While there, I observed a SI well site and access road
 During this inspection the following possible compliance issues were observed:
 Access: Rule 600 Corrective action date of 12-15-21 See photos.
 Weather conditions: Cloudy and dry.
 This inspection is due to a complaint submitted to the COGCC doc#402865422 in regards to the condition of bridge on access road.
 A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.
 This is a summary of inspection report.

silverr

11/15/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
693505826	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5581512