

FORM
INSPRev
X/20

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/16/2021

Submitted Date:

11/16/2021

Document Number:

693505829

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
317765 _____ Silver, Randy _____ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: _____ 46290 _____
Name of Operator: KP KAUFFMAN COMPANY INC _____
Address: 1675 BROADWAY, STE 2800 _____
City: _____ DENVER _____ State: _____ CO _____ Zip: _____ 80202 _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 3 _____ Number of Comments
0 _____ Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Adamczyk, Megan		megan.adamczyk@state.co.us	
,	303-825-4822	cogcc@kpk.com	All Inspections
Watzman, Ross	(303) 825-4822	rwatzman@kpk.com	all inspections.

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
239943	WELL	PR	03/20/1995	OW	123-07731	A L LUFT 1	PR

General Comment:

Inspected Facilities

Facility ID: 239943 Type: WELL API Number: 123-07731 Status: PR Insp. Status: PR

Complaint

Comment: Inspection in response to complaint.
 Field Inspector Assigned: Randy Silver
 Complaint Received
 Date: 11-15-2021
 Complaint Contacted: Yes via phone
 Date: 11-15-2021 Time: 2:37PM
 Location ID #317765
 Location name: AL Luft #1
 Inspection Document # 693505825
 Complaint inspection document #693505829
 Complaint Document #402865422
 Nature of Complaint: Access
 Field Inspector Actions:
 On 11-15-2021, I Randy Silver area field inspector was assigned a complaint received by COGCC staff in reference to Road access. The complainant Patrick Hladky 13608 County road 18.5 Fort Lopton CO stated the issues were occurring on his property.
 On 11-15-2021, I attempted to make contact with the complainant who indicated his concern with a irrigation ditch bridge. He is worried about the integrity of bridge decking. Complainant had to put dirt on each end of bridge to be able to cross. Complainant stated he has reported this to KPK on multiple occasions. He also stated he had been performing weed mitigation on access road and location due to the lack of maintenance from KPK.
 I performed a complete site inspection of the oil and gas location and associated wells in the area. At time of inspection, I inspected said bridge. It appears bridge decking is rotting and is in need of repair as this is the only access to the well I did issue a corrective action to KPK for the bridge being repaired.
 Weather conditions: Cloudy
 No violation of COGCC rules were observed at the time of the inspection.
 All information reviewed and site inspection information has been submitted to the COGCC for further review.

Corrective Action:

Date: