

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/16/2021

Submitted Date:

11/16/2021

Document Number:

693505886

FIELD INSPECTION FORMLoc ID 321346 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10459

Name of Operator: EXTRACTION OIL & GAS INC

Address: 370 17TH STREET SUITE 5200

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

6 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		COGCCInspections@extracti onog.com	All Inspectors

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
206753	WELL	SI	05/01/2020	GW	013-06248	THRONDSO 3-2	SI

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	
Corrective Action:	Date: _____

Good Housekeeping:		
Type	DEBRIS	
Comment:	Dead weed in and around well head	
Corrective Action:	Comply with rule 606	Date: 12/16/2021

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

Fencing/:		
Type	WELLHEAD	
Comment:	Steel rod	
Corrective Action:		Date:

Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

Venting:		
Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:		
Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 206753 Type: WELL API Number: 013-06248 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily AbandonedReminder: EQUIPMENT ONSITEComment: At time of inspection well head is LOTO.Corrective Action: Date: **COGCC Comments**

Comment

User

Date

COGCC Inspection Report Summary
 On Tuesday November 16, 2021 at approximately 1:04PM, I, Inspector Randy Silver, conducted an on-site inspection.
 Location: Throndson #3-2
 Operator: Extraction
 API#: 013-06248
 County: Bolder
 While there, I observed a SI well site.
 During this inspection the following possible compliance issues were observed:
 Debris: Rule 606 Corrective action date of 12-16-21
 Weather conditions: Cloudy and windy
 A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.
 This is a summary of inspection report.

silverr

11/16/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693505887	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5582301