



Linda 12-19



Installed appropriate fittings to allow bradenhead visual inspection as per Rule 419.a