

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/09/2021

Submitted Date:

11/09/2021

Document Number:

699503334

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: MEDINA, JUSTIN On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 76859
Name of Operator: SCHREIDER & COMPANY INC
Address: 9227 E LINCOLN AVE SUITE 200
City: LONE TREE State: CO Zip: 80124

Findings:

- 6 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|---------------|----------------|-------------------------|---------------------------------|
| C, RUDY | 303-659-8203 | darnold@agcsi.com | All Inspections |
| Kelly, George | (602) 697-2484 | schreiderco@outlook.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------------|-------------|
| 203561 | WELL | SI | 07/01/2018 | GW | 001-09121 | IVOL FERGUSON 14-33 | SI |

General Comment:

(This area is intentionally left blank for general comments.)

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

| | | | |
|--------------------|--|-------|-------------------|
| Type | OTHER | | |
| Comment: | No Access roads. At time of inspecion electric fence was installed across gate, unable to access location | | |
| Corrective Action: | L Location is within a designated setback location, maintain and repair access roads per Rule 604.c.(2)S. Corrective Action Date 7/71/2020 See attached photos | Date: | <u>07/17/2020</u> |
| Type | WEEDS | | |
| Comment: | Weeds | | |
| Corrective Action: | Location is within a designated setback location, remove Weeds per Rule 603 f. Corrective Action Date 7/6/2020 | Date: | <u>07/06/2020</u> |
| Type | OTHER | | |
| Comment: | Building(s) in disrepair (around Pump jack motor). | | |
| Corrective Action: | Inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. Corrective Action Date 7/17/2020 | Date: | <u>07/17/2020</u> |

Overall Good:

Spills:

| Type | Area | Volume | | |
|------|------|--------|--|--|
| | | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Inspected Facilities

Facility ID: 203561 Type: WELL API Number: 001-09121 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____
 Comment:
 Corrective Action: Date: _____

BradenHead

Date of Last Brhd Test: 09/25/2019 Annual Brhd Completed? Yes
 Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____
 End Surf Csg Pressure: 0
 Comment:
 Corrective Action: Date: _____

COGCC Comments

| Comment | User | Date |
|---|---------|------------|
| <p>COGCC Inspection Report Summary On 11/8/21 at approximately 1500 I, Inspector Justin Medina conducted an on-site inspection at: Well Name- IVOL FERGUSON 14-33 Company Name- Schreider & Company INC API- 05-001-09121 In Adams County Colorado. While there, I observed SI well This is a follow up inspection from document # 700900162 Corrective Actions are Delinquent During this inspection the following possible compliance issues were observed: No Access roads. At time of inspection electric fence was installed across gate, unable to access location L Location is within a designated setback location, maintain and repair access roads per Rule 604.c.(2)S. Corrective Action Date 7/71/2020 Weeds Location is within a designated setback location, remove Weeds per Rule 603 f. Corrective Action Date 7/6/2020 Building(s) in disrepair (around Pump jack motor). Inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. Corrective Action Date 7/17/2020 A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p> | medinaj | 11/09/2021 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 402869023 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5579161 |
| 699503335 | Inspection pictures | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5579154 |