

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/16/2021

Submitted Date:

11/16/2021

Document Number:

693505890

FIELD INSPECTION FORM

Loc ID 321371 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10459

Name of Operator: EXTRACTION OIL & GAS INC

Address: 370 17TH STREET SUITE 5200

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

4 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
,		COGCCInspections@extracti onog.com	All Inspectors

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
206787	WELL	SI	05/01/2020	GW	013-06282	HEWITT 2-22	SI

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign not updated to reflect current operator		
Corrective Action:	Install sign to comply with Rule 605.g.	Date:	12/16/2021

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 206787 Type: WELL API Number: 013-06282 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily AbandonedReminder: EQUIPMENT ONSITEComment: At time of inspection well head was LOTOCorrective Action: Date: **COGCC Comments**

Comment

User

Date

COGCC Inspection Report Summary
 On Tuesday November 16, 2021 at approximately 2:04PM, I, Inspector Randy Silver, conducted an on-site inspection.
 Location: Hewitt #2-22
 Operator: Extraction
 API#: 013-06282
 County: Bolder
 While there, I observed a SI well site.
 During this inspection the following possible compliance issues were observed:
 Sign: Rule 605 g Corrective action date of 12-16-21
 Weather conditions: Cloudy and windy
 A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.
 This is a summary of inspection report.

silverr

11/16/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402872301	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5582309
693505891	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5582303