

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402786835

Date Received:  
09/20/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10766  
Name of Operator: ARKOMA OPERATIONS LLC  
Address: 2121 S COLUMBIA AVE SUITE 101  
City: TULSA State: OK Zip: 74114  
Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Price, Andrew</u>	<u>918-260-8324</u>	<u>aprice@arkomaops.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 693903551  
Inspection Date: 10/11/2021 FIR Submit Date: 08/18/2021 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: CATAMOUNT ENERGY PARTNERS LLC Company Number: 10464  
Address: 1001 17TH STREET STE 1160  
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 333792

Location Name: JACQUES-N33N8W Number: 27SENW County: LA PLATA  
Qtrqr: SENW Sec: 27 Twp: 33N Range: 8W Meridian: N  
Latitude: 37.076487 Longitude: -107.707861

FACILITY - API Number: 05-067-00 Facility ID: 454865

Facility Name: Jaques Number: 9  
Qtrqr: SENW Sec: 27 Twp: 33N Range: 8W Meridian: N  
Latitude: 37.076487 Longitude: -107.707861

CORRECTIVE ACTIONS:

1 ☒ CA# 154983

Corrective Action: Remove and properly manage/control discharged road materials from the access road. Date: 09/18/2021

Response: CA COMPLETED Date of Completion: 09/17/2021

Operator Comment: Removed road material, cleared out diversions and road cut outs.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

2 ☒ CA# 154984

Corrective Action: -Stormwater erosion needs to be controlled along the access road. Stormwater controls need to be installed to stabilize erosion within the southwestern project area. Additionally, all stormwater BMPs within project diversions need maintenance and repair/and or replacement. Corrective action date: 9/18/2021.

Date: 09/18/2021

Response: CA COMPLETED

Date of Completion: 09/17/2021

Operator Comment: Cleaned out and deepened roadside diversions and cut outs.  
Cleaned out and improved diversion ditches along the ROW at the Southwester well pad, Rock check dams were rebuilt and reinforced.  
Reseeded bare ground along the western and southern portions of the well pad.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jaime Pugh

Signed:

Title: Engineering Analyst

Date: 9/20/2021 1:54:05 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402786835	FIR RESOLUTION SUBMITTED
402816830	Jaques 1, 5F, 9 9-18-21 (693903551) remediation

Total Attach: 2 Files