

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/23/2021

Submitted Date:

11/29/2021

Document Number:

700703584**FIELD INSPECTION FORM**Loc ID 315995 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 200502Name of Operator: 31 OPERATINGAddress: 3021 RIDGE RD #156City: ROCKWALL State: TX Zip: 75032**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**9 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, COGCC		mike.leonard@state.co.us	
Thomson, Bud		BLThomps@BLM.gov	
operating, 31		kfreeman@31operating.com	
, COGCC		kelly.rosenberg@state.co.us	<a href="#">regulatory/hearings</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
231892	WELL	TA	12/01/1992	GW	103-09563	WILDLIFE 3-1	TA

**General Comment:**[COGCC Inspection Report Summary](#)

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

On Tuesday 11/23/2021 at approximately 1200, I, Inspector Scott Ramsey, conducted a routine inspection at 31 Operating Wildlife #3-1, at Location # 314981 in Rio Blanco county Colorado.

While there, I observed no production operations. Well is temporarily abandoned. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area. There is no evidence of tracking pad at time of inspection.

During this inspection the following compliance issues were observed:

1. No evidence of tracking control BMP's.
2. Locations weeds have turned into debris throughout location.
3. Access shows signs of lack of stabilization and erosion.
4. One dead man is not properly marked.

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	See stormwater		
Corrective Action	L		Date:
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	1-800-209-9762/911		
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	DEBRIS		
Comment:	Locations weeds have turned into debris throughout location.		
Corrective Action:	Remove all debris		Date: 12/31/2021
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Equipment:</b>			
Type: Bradenhead	# 1		corrective date
Comment:			
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Well head is T/A		
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:	One deadman is not marked properly		
Corrective Action:	Mark or remove deadman		Date: 12/31/2021
<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:			Date:
<b>Flaring:</b>			
Type			

Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	231892	Type:	WELL	API Number:	103-09563	Status:	TA	Insp. Status:	TA
Idle Well									
Purpose: <input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned									
Reminder: _____									
Comment: Last MIT done 6/1/2017									
Corrective Action: _____									
Date: _____									

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction	Fail			
		Ditches	Fail			

Comment: 1. Access shows signs of lack of stabilization and erosion.  
2. No evidence of tracking control BMP's.

Corrective Action: Provide proof of tracking control BMP's and Install or repair required BMPs

Date: 12/31/2021

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700703592	Photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5591150">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5591150</a>