

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/30/2021

Submitted Date:

11/30/2021

Document Number:

701102280**FIELD INSPECTION FORM**Loc ID 314686 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 12930Name of Operator: CALCO DBA CALLISTER COAddress: 1230 W 1400 NCity: LEHI State: UT Zip: 84043**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
Callister, Jan	801-487-4721	jec-apex@outlook.com	
, Engineering		dnr_cogccengineering@state.co.us	All engineering
Thompson, Bud		BLThomps@BLM.gov	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
229262	WELL	TA	06/01/2021	GW	103-06357	CALLISTER- GOVERNMENT 3	TA

General Comment:

A follow up inspection of documents:

- 1) FIR 679701565 dated 10-30-2018.
- 2) Warning letter 401622289 dated 11-28-2018.
- 3) FIR 679703764 dated 10-30-2018.

The following compliance issues are uncompleted:

- 1) Acquire MIT or plug well.
- 2) Unused equipment.

LocationOverall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign no at well head		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	911	Date:	
Corrective Action:			

Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Wood, pipe fittings, and pump jack.		
Corrective Action:	Comply with Rule 606.	Date:	06/28/2021

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Bradenhead	#		
Comment:	Bradenhead open to atmosphere.		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	Not in use		
Corrective Action:		Date:	

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 229262 Type: WELL API Number: 103-06357 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: Last recorded production 9-1-2013. Swab test on 10-26-2020. No current MIT on file.Corrective Action: Perform successful mechanical integrity test. If a successful MIT can not be performed within 30 day CA time the well must be plugged within 3 months per Rule 417 and 210. Date: 07/31/2021**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701102281	Inspection 701102280 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5591945