

Inspection Photos
Location Name: Federal 30-4
API: 05-051-06022



Federal 30-4 location photo.



Federal 30-4 production equipment.

API: 05-051-06022



Federal 30-4 produced water AST. Earthen berm appears to have inadequate capacity, as noted by previous inspector.



Sediment pile in NW corner of location.