

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402893339

Date Received:

12/08/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10758

Name of Operator: OGRIS OPERATING LLC

Address: PO BOX 53467

City: MIDLAND State: TX Zip: 79710

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

ATWATER BONNIE

batwater@ogrisop.com

Fitzgerald, Edie

efitzgerald@ogrisop.com

Gee, Greg

903-987-0353

ggee@ogrisop.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 690202109

Inspection Date: 09/28/2021

FIR Submit Date: 09/29/2021

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: TIMBER CREEK OPERATING LLC

Company Number: 10672

Address: 6295 GREENWOOD PLAZA BLVD #100

City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

LOCATION - Location ID: 309122

Location Name: GOLDEN EAGLE-633S67W Number: 29SESE County: LAS ANIMAS

Qtrqtr: SESE Sec: 29 Twp: 33S Range: 67W Meridian: 6

Latitude: 37.137485 Longitude: -104.904999

FACILITY - API Number: 05-071- -00 Facility ID: 288299

Facility Name: GOLDEN EAGLE Number: 29-16

Qtrqtr: SESE Sec: 29 Twp: 33S Range: 67W Meridian: 6

Latitude: 37.137485 Longitude: -104.904999

CORRECTIVE ACTIONS:

1 ☒ CA# 156296

Corrective Action: Control and contain spills/releases and clean up per Rule 912.a.

Date: 08/05/2021

Response: CA COMPLETED

Date of Completion: 09/30/2021

Operator Comment: THE WATER IN THE CELLAR WAS PUMPED OUT BY VAC-TRUCK. THE LOCATION WAS BACK DRAGGED TO ELIMINATE THE HARDPAN DISCOLORATION.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

2 ☒ CA# 156297

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 09/01/2021

Response: CA COMPLETED

Date of Completion: 11/30/2021

Operator  
Comment:

THE SEDIMENT WAS REMOVED FROM THE CATTLE GUARD. THE LEASE ROAD WAS REGRADED AND THE ROAD SURFACE WAS CROWNED TO CREATE SHEET FLOW. CULVERTS WERE MAINTAINED, SEDIMENT ACCUMULATION REMOVED. ROCK SOCK CHECKS WERE PLACED IN THE BAR DITCH FOR SEDIMENT CONTROL. WATER CALLOUTS WERE INSTALLED. SEE ATTACHED PHOTO LOG FOR DETAILS.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: ALL CORRECTIVE ACTIONS HAVE BEEN ADDRESSED. SEE ATTACHED PHOTO LOG FOR DETAILS.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Edie Fitzgerald

Signed: \_\_\_\_\_

Title: Sr. Environmental Tech.

Date: 12/8/2021 4:01:03 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402893339	FIR RESOLUTION SUBMITTED
402893379	PHOTO LOG

Total Attach: 2 Files