

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type PUMP JACK

Comment: Hog fence around counter weight guard.

Corrective Action:

Date:

Equipment:

corrective date

Type: Ancillary equipment # 1

Comment: Electric equipment

Corrective Action:

Date:

Type: Bradenhead # 1

Comment: Plumbed to surface

Corrective Action:

Date:

Type: Prime Mover # 1

Comment: Electric motor

Corrective Action:

Date:

Type: Pump Jack # 1

Comment:

Corrective Action:

Date:

Venting:

Yes/No NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 241009 Type: WELL API Number: 123-08797 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 07/15/2020 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 12 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: Annual bradenhead test is not current. Contact COGCC engineering. Provide Monthly Monitoring data. 12/11/2021

Corrective Action: Comply with COGCC annual bradenhead testing rules. Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On 12/1/21 at approximately 1500 I, Inspector Justin Medina conducted an on-site inspection at: Well Name- Harriet W Lucke 2 Company Name- KPK API- 05-123-08797 In Weld County Colorado. While there, I observed SI well. During this inspection the following possible compliance issues were observed: Annual bradenhead test is not current. Contact COGCC engineering. Provide monthly monitoring data. Comply with COGCC annual bradenhead testing rules. Other corrective actions from Directors orders pursuant to rule 901. A. Document # 1310550 may still be active. This inspection does not nullify previous corrective actions from Document # 1310550 A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	medinaj	12/01/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402887305	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5596450
699503376	inspection pictures	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5596445