

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402825309

Date Received:
09/29/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 69805
Name of Operator: PETROX RESOURCES INC
Address: 12600 W COLFAX AVENUE #C-440
City: LAKEWOOD State: CO Zip: 80215

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Clark, Mike</u>	<u>970-878-5594</u>	<u>mike.petrox@gmail.com</u>
<u>Nystrom, Dusty</u>		<u>nystrow@yahoo.com</u>
<u>Brown, Walt</u>	<u>970-385-1372</u>	<u>wabrown@fs.fed.us</u>
<u>Clark, Ryan</u>	<u>303-803-3998</u>	<u>Ryan@petrox-resources.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 693903650
Inspection Date: 09/13/2021 FIR Submit Date: 09/14/2021 FIR Status: _____

Inspected Operator Information:

Company Name: PETROX RESOURCES INC Company Number: 69805
Address: 12600 W COLFAX AVENUE #C-440
City: LAKEWOOD State: CO Zip: 80215

LOCATION - Location ID: 320886

Location Name: FOSSET GULCH UNIT 9U-M34N5W Number: 9NWNE County: ARCHULETA
Qtrqtr: NWNE Sec: 9 Twp: 34N Range: 5W Meridian: M
Latitude: 37.209670 Longitude: -107.393880

FACILITY - API Number: 05-007-00 Facility ID: 277656

Facility Name: FOSSET GULCH UNIT 9U Number: 2
Qtrqtr: NWNE Sec: 9 Twp: 34N Range: 5W Meridian: M
Latitude: 37.209670 Longitude: -107.393880

CORRECTIVE ACTIONS:

1 CA# 155804

Corrective Action: Control weeds. Date: 10/15/2021

Response: CA COMPLETED Date of Completion: 09/24/2021

Thistle on the north slope and west slope were sprayed on 9/24/2021, Photos attached. Weeds will monitored

Operator Comment: Fall of 2021 and Spring 2022- Fall 2022

COGCC Decision: Approved pending re-inspection

COGCC Representative:

2 CA# 155805

Corrective Action: -Stormwater and erosion controls need to be installed to stabilize erosion on the well pad cut-slope. Stormwater and erosion controls need to be installed and maintained; according to good engineering practices, until soils are stabilized with desirable perennial vegetation. Corrective action date: 10/15/2021

Date: 10/15/2021

Response: CA COMPLETED

Date of Completion: 09/28/2021

Operator Comment: Waddles were installed on 9/28/2021 on cut slope to help stabilize soil. Area will be monitored weekly to determine if further erosional controls are needed. Please find photos attached.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Ryan Clark

Signed: _____

Title: V.P. Engineering

Date: 9/29/2021 9:07:19 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402825309	FIR RESOLUTION SUBMITTED
402826192	Corrected Action Photos

Total Attach: 2 Files