

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402890779

Date Received:
12/07/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10758

Name of Operator: OGRIS OPERATING LLC

Address: PO BOX 53467

City: MIDLAND State: TX Zip: 79710

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Gee, Greg

903-987-0353

ggee@ogrisop.com

ATWATER BONNIE

batwater@ogrisop.com

Fitzgerald, Edie

efitzgerald@ogrisop.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 690202111

Inspection Date: 09/28/2021

FIR Submit Date: 09/29/2021

FIR Status: _____

Inspected Operator Information:

Company Name: TIMBER CREEK OPERATING LLC

Company Number: 10672

Address: 6295 GREENWOOD PLAZA BLVD #100

City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

LOCATION - Location ID: 309141

Location Name: GOLDEN EAGLE-633S67W Number: 32NWNW County: LAS ANIMAS

Qtrqtr: NWN Sec: 32 Twp: 33S Range: 67W Meridian: 6

Latitude: 37.134960 Longitude: -104.918450

FACILITY - API Number: 05-071-00 Facility ID: 288584

Facility Name: GOLDEN EAGLE Number: 32-4

Qtrqtr: NWN Sec: 32 Twp: 33S Range: 67W Meridian: 6

Latitude: 37.134960 Longitude: -104.918450

CORRECTIVE ACTIONS:

1 CA# 156298

Corrective Action: Comply with Rule 1003.f.

Date: 09/15/2021

Response: CA COMPLETED

Date of Completion: 10/06/2021

THE NOXIOUS WEEDS WERE TREATED ON 10/06/21.

Operator
Comment:

COGCC Decision: **Not Approved**

COGCC Representative: The attached photo shows the biennial Noxious weed still present. Seed heads should have been bagged and removed. Ongoing weed control will need to be performed.

2 ☒ CA# 156299

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 09/01/2021

Response: CA COMPLETED

Date of Completion: 12/01/2021

Operator
Comment:

ROCK SOCK CHECKS WERE PLACED IN THE BAR DITCH FOR SEDIMENT CONTROL. THE SEDIMENT ACCUMULATION WAS REMOVED FROM THE CULVERT INLET.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: ALL CORRECTIVE ACTIONS HAVE BEEN ADDRESSED. SEE ATTACHED PHOTO LOG FOR DETAILS.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Giena Ward

Signed:

Title: Environmental Technician

Date: 12/7/2021 10:05:54 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402890779	FIR RESOLUTION SUBMITTED
402890821	Photo Log

Total Attach: 2 Files