

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/21/2021

Submitted Date:

12/21/2021

Document Number:

693506167

FIELD INSPECTION FORMLoc ID 320509 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Watzman, Ross	(303) 825-4822	rwatzman@kpk.com	all inspections.
,	303-825-4822	cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
272094	WELL	SI	10/01/2021	OW	001-09504	SACK 8-11	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign starting to fade may need to be replaced in near future.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 272094 Type: WELL API Number: 001-09504 Status: SI Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 10/27/2021 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: -- Fluid Type: End Surf Csg Pressure: --

Comment:

Corrective Action:

Date:

Workover

Comment: This a KPK rig. Last inspection Doc#693506109 crew had informed me they were just attaching houses head and leaving. Crew is still on site at time of inspection. Spoke with rig operator he informed me they were told to do a pump change after I had left last inspection on 12-16-21. At time of inspection crew was reattaching horses head to walking beam and rigging down.

Corrective Action:

Date:

COGCC Comments

Comment

User

Date

Inspeciton due to form 42 notice.

silverr

12/21/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693506168	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5613931